

HELL BRIDGE - NORWAY

In 2000, ZINGA was applied on the steel structures of the Hell Bridge in Norway.
The bridge was inspected in 2007 and no touch-ups were required.



System:
Blasting to SA 2,5 and Rz 50-70µm
ZINGA 2 x 60 µm DFT

HELL BRIDGE - NORWAY

On 13 November 2018, **18 years after the original application**, a visual inspection was carried out by ZINGA Belgium and ZINGA Norway.

Not any corrosion nor any adhesion defects could be spotted.



Seaside view