

WATER RESERVOIR – BRAZIL

In 2013, a water reservoir tower located near beach houses in Sao Paulo, was treated with ZINGA.

The water reservoirs were badly corroded. After dismantling of the towers, they were treated in a work shop. The surface was cleaned and blasted before a first application of ZINGA.

The external ZINGA layer was overcoated with a UV resistant PU, the inside was coated with an epoxy suitable for contact with water.

System:

- ZINGA 60 µm DFT
- + Epoxy topcoat (inside)
- + PU topcoat (outside)

